



Accessible Products Company
2122 W. 5th Pl.
Tempe AZ 85281

Phone: 480-967-8888
Fax: 480-894-6255

RE: Davis Schools Administration Building Pipe Insulation
TechLite Insulation Warranty

Please note that in order to maintain the full product warranty on TechLite® insulation products, all recommended factory thickness selection charts and installation guidelines must be followed.

Failure to install the product correctly, according to standard industry practices and factory recommended procedures, could invalidate product warranty claims.

A reasonable margin of safety needs to be figured into the insulation thickness due to local conditions that can occur. If piping is in an equipment room with unconditioned air then high ambient air temperatures, combined with multiple pipes or other radiant heat sources nearby, could cause the jacket surface temperatures of the PVC insulation to exceed recommended levels, resulting in distorted jacket and possibly split seams or ill-fitting covers.

Thank you,
Dave Wenzlick
Engineering Dept.
TechLite® Insulation